



## HERON SUZUKI

Heron Suzuki GB Limited,  
87 Beddington Lane, Croydon, Surrey England, CR0 4TD.  
Telephone: 01-689 3471 Telex: 21138 Cables: Suzuki Croydon

NB/D/TEC

May, 1976.

### TECHNICAL BULLETIN NO: 15

Subject - Carburettor Jetting

Applicable Model - GT550M, A

Effective Engine or Frame No:

Engine No: GT550 - 65092

### PROBLEM

We have found that the left carburettor on the GT550 produces slightly too lean mixture under high speed conditions causing uneven heat among the three cylinders.

### MODIFICATION

We have modified the main jet size for the left carburettor from No: 102.5 to No: 105. This change accompanies an alteration of the identification mark on the carburettor body. The following chart shows the details.

I T E M	OLD	NEW
Main Jet for left carburettor	No:102.5	No:105
Identification mark on left carburettor	34621	34622

Note: Right and middle carburettors remain unchanged.

### APPLICATION

This modification has been carried out on and from the engine number GT550-65092.

Chairman & Man. Dir. P. James Agg  
Joint Chairman: G. M. Ronson  
Directors: P. S. Reynolds A. I. Goldman FCA  
Edna M. Calder M. E. Knight L. G. Clark



Registered Office  
Kingsley House, 12 Trojan Way,  
Croydon England, CR0 4XO.  
Registered England No. 7501587

TEC15

- 2 -

PARTS SUPPLY DATA

PART NAME	OLD PART NO.	NEW PART NO.	Q'TY	AVAILABILITY
Carburettor Assy	13200-34621	13200-34622	1	New only
Left Carburettor Assy	13203-34621	13203-34622	1	New only
Main Jet for Left Carburettor	09491-20004	09491-21003	1	Both new and old

NOTE

Should this problem be experienced with this model, please carry out the above modification.